

Elco Industrial Parts Catalog

Axiparts Global Industrial RFQ Platform

Email: info@axiparts.com

Website: <https://axiparts.com>

Premium RFQ catalog for Elco industrial spare parts, MRO components and replacement products. Every listed product is linked directly to its live RFQ product page.

Brand: Elco

Listed Products in This PDF: 232

Catalog URL: <https://axiparts.com/catalogs/brands/elco.pdf>

| Part Number | Product Description | Live RFQ Link |
|----------------|--|---------------------------------------|
| 0401025 | 0401025 SUCTION ELEC. FAN 34W. | Open Product RFQ Page |
| 0402002 | 0402002 MOTORS 3RGB 50-30/1 | Open Product RFQ Page |
| 0402004 | 0402004 Motor | Open Product RFQ Page |
| 0402009 | 0402009 engine 6V/2 | Open Product RFQ Page |
| 0402014 | 0402014 engine 6V/4 | Open Product RFQ Page |
| 0402015 | 0402015 MOTORS 3RGB 50-30-6V/14 | Open Product RFQ Page |
| 0402043 | 0402043 Motor | Open Product RFQ Page |
| 0403081 | 0403081 | Open Product RFQ Page |
| 1 | 1 BT 45-40-1V NA Fan motor | Open Product RFQ Page |
| 10721015 | 10721015 WING | Open Product RFQ Page |
| 11060 | 11060 230 Va | Open Product RFQ Page |
| 1370.....CNS | 1370.....CNS 2-15/200 fan | Open Product RFQ Page |
| 138616102 | 138616102 fan motor | Open Product RFQ Page |
| 1516000573 | 1516000573 - VNT25.40/030 motor | Open Product RFQ Page |
| 1519000172 | 1519000172 - 3BTM25.20.6V.0/1 motor | Open Product RFQ Page |
| 1519000484 | 1519000484 - GMV 3BTM.CO.25.20.0/14 40171316 Original Spare Part | Open Product RFQ Page |
| 1519000910 | 1519000910 - 3RGB50.30.6V/14 4010694 MOTOR | Open Product RFQ Page |
| 1519002051 | 1519002051 - 40171515 | Open Product RFQ Page |
| 1893000474 | 1893000474 | Open Product RFQ Page |
| 1BT45.40.6VNA | 1BT45.40.6VNA BTNB46TB0142 Motor | Open Product RFQ Page |
| 1BT60.30.1VNO | 1BT60.30.1VNO BTNM21TB0065 Motor | Open Product RFQ Page |
| 1FG385.69.5VNA | 1FG385.69.5VNA FGFB45TB0337R Fan engine | Open Product RFQ Page |
| 1HO630.57.4VNA | 1HO630.57.4VNA HOFB44TB0247S Motor | Open Product RFQ Page |
| 2 | 2 VC 146-216-S SHAFT FAN MOTOR COIL LEFT WING | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|----------------------|--|---------------------------------------|
| 2196/ | 2196/ PRI-32 Original Spare Part | Open Product RFQ Page |
| 22321095 | 22321095 | Open Product RFQ Page |
| 22321101 | 22321101 | Open Product RFQ Page |
| 3- | 3- 042-100 Autotransformer | Open Product RFQ Page |
| (3-042-033) | (3-042-033) 12201620 | Open Product RFQ Page |
| 3-042-100 | 3-042-100 (12201618) Autotransformateur | Open Product RFQ Page |
| 3.15μ | 3.15μ permanent capacitor | Open Product RFQ Page |
| 3750253 | 3750253 NEXTRON-Gasstrecke | Open Product RFQ Page |
| 3750511 | 3750511 Original Spare Part | Open Product RFQ Page |
| 3750526 | 3750526 Original Spare Part | Open Product RFQ Page |
| 3750571 | 3750571 ELCO Monoblock Gasgebläsebrenner | Open Product RFQ Page |
| 38TB | 38TB 45-40-6V- 0/4 Fancoil Motor | Open Product RFQ Page |
| 3BTB | 3BTB 45 45-40-6v- 0/4 Motor | Open Product RFQ Page |
| 3BTB30.30.0/8 | 3BTB30.30.0/8 40101821/50 Motor | Open Product RFQ Page |
| 3BTB35.30.0/1 | 3BTB35.30.0/1 E40101115 Motor | Open Product RFQ Page |
| 3BTB35.30.6V.0.1 | 3BTB35.30.6V.0.1 for 3BTB-C0 30-30-A-0/18 motor for fan | Open Product RFQ Page |
| 3BTB45.40.0/3 | 3BTB45.40.0/3 40101533 Motor | Open Product RFQ Page |
| 3BTB45.40.6V.0/4 | 3BTB45.40.6V.0/4 40101508 Motor | Open Product RFQ Page |
| 3BTB50.40.6V.0.1 | 3BTB50.40.6V.0.1 | Open Product RFQ Page |
| 3BTB50.40.6V.0.2 | 3BTB50.40.6V.0.2 Motor | Open Product RFQ Page |
| 3BTB-C0 | 3BTB-C0 45-40-0/33, not available, replaced by 3BTB50.40.6V.0.2 | Open Product RFQ Page |
| 3BTB-CO | 3BTB-CO 35-40-A-0/6 obsolete, alternative 3BTB35.30.6V.0.1 + 22321098 Engine | Open Product RFQ Page |
| 3BTB.CO.20.30.0/11 | 3BTB.CO.20.30.0/11 40171814 | Open Product RFQ Page |
| 3BTB.CO.30.30.A.0/18 | 3BTB.CO.30.30.A.0/18 40171469 motor+ fan | Open Product RFQ Page |
| 3BTB-CO-35-40-A-0/5 | 3BTB-CO-35-40-A-0/5 obsolete, replacement 3BTB 35.30.6V.0.1 Engine | Open Product RFQ Page |
| 3BTB.CO.38.40.A.0/3 | 3BTB.CO.38.40.A.0/3 Original Spare Part | Open Product RFQ Page |
| 3BTB.CO.40.40.A.0/25 | 3BTB.CO.40.40.A.0/25 40171596 | Open Product RFQ Page |
| 3BTB.CO.45.40.0/22 | 3BTB.CO.45.40.0/22 BTNB41TB0054S 40171515 | Open Product RFQ Page |
| 3BTB-CO-45-40-3V-0/2 | 3BTB-CO-45-40-3V-0/2 - OEM PRODUCT. fan | Open Product RFQ Page |
| 3BTB.CO.45.40.A.0/13 | 3BTB.CO.45.40.A.0/13 40171325 | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|----------------------|--|---------------------------------------|
| 3BTB-CO-45-40-A-0/21 | 3BTB-CO-45-40-A-0/21 FAN UNIT | Open Product RFQ Page |
| 3BTB.CO.45.40.A.0/22 | 3BTB.CO.45.40.A.0/22 40171453 alternative EM-4-50/3DS | Open Product RFQ Page |
| 3BTB-CO-55-45-A-0 | 3BTB-CO-55-45-A-0 - alternative 0403081 Fan | Open Product RFQ Page |
| 3BTB.CO.60.45.A.0/5 | 3BTB.CO.60.45.A.0/5 40171587 | Open Product RFQ Page |
| 3BTM | 3BTM CO 25 20 0 22 - 40171513 | Open Product RFQ Page |
| 3BTM25.20-A-0/122 | 3BTM25.20-A-0/122 Motor | Open Product RFQ Page |
| 3BTM45.40/1 | 3BTM45.40/1 40101602F Motor | Open Product RFQ Page |
| 3BTM-C0-25-20-3V-0/1 | 3BTM-C0-25-20-3V-0/1 obsolete; alternative 3BTB35.30.6V.0.1 + ref 22321098 Motor | Open Product RFQ Page |
| 3BTM-CO | 3BTM-CO 25-20-0/22 | Open Product RFQ Page |
| 3BTM.CO.10.20.6V.0/1 | 3BTM.CO.10.20.6V.0/1 40171111 | Open Product RFQ Page |
| 3BTM.CO.170.40.2.0/1 | 3BTM.CO.170.40.2.0/1 40171175 Fan + Motor | Open Product RFQ Page |
| 3BTM.CO.25.20.0/20 | 3BTM.CO.25.20.0/20 | Open Product RFQ Page |
| 3FGB | 3FGB 370.70.3V/8. Motor | Open Product RFQ Page |
| 3FGB-00100-40-6V/24E | 3FGB-00100-40-6V/24E obsolete, alternative 3FGB100.40.6V.26 Fan | Open Product RFQ Page |
| 3FGB100-40-6V11 | 3FGB100-40-6V11 not available, alternative 48-4-100/6DSL (brand Remco), or 3FGB100.40.6V.26 + 22321101 | Open Product RFQ Page |
| 3FGB100.40.6V.26, | 3FGB100.40.6V.26, code: 12201018 Motor | Open Product RFQ Page |
| 3FGB120.40.5V/4 | 3FGB120.40.5V/4 Motor | Open Product RFQ Page |
| 3FGB320.63.3V/1 | 3FGB320.63.3V/1 40101338 MOTOR | Open Product RFQ Page |
| 3FGB400.63.4V/1 | 3FGB400.63.4V/1 Motor | Open Product RFQ Page |
| 3FGB65.38.6V/1000 | 3FGB65.38.6V/1000 40103003 Motor | Open Product RFQ Page |
| 3FGB-C0 | 3FGB-C0 110-40-6V/V, not available, replaced by 3FGB100.40.6V.26 Motor | Open Product RFQ Page |
| 3FGB-CO | 3FGB-CO 85-38-6V/2 Motor | Open Product RFQ Page |
| 3FGB-CO-180-69-5V/3 | 3FGB-CO-180-69-5V/3 | Open Product RFQ Page |
| 3FGB.CO.465.70.4V/1 | 3FGB.CO.465.70.4V/1 40171243 | Open Product RFQ Page |
| 3FGB.CO.85.38.6V/3 | 3FGB.CO.85.38.6V/3 FGFB46TB0194S 40171588 Original Spare Part | Open Product RFQ Page |
| 3FGB-COD | 3FGB-COD 100-40-5V/2 OEM blower unit | Open Product RFQ Page |
| 3FGB.COD.120.40.5V/2 | 3FGB.COD.120.40.5V/2 40171302 | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|---------------------|---|---------------------------------------|
| 3FGM | 3FGM 90-40-7V/1 40101728/1 Fan motor | Open Product RFQ Page |
| 3FGM110.40.6V/1 | 3FGM110.40.6V/1 | Open Product RFQ Page |
| 3FGM120.45/1 | 3FGM120.45/1 40101245 motor | Open Product RFQ Page |
| 3FGM90.40.7V/1 | 3FGM90.40.7V/1 40101728/50 Motor | Open Product RFQ Page |
| 3FGM-C0 | 3FGM-C0 90-40-7V/1 Motor | Open Product RFQ Page |
| 3FGM.CO.150.38.6V/1 | 3FGM.CO.150.38.6V/1 40171610 | Open Product RFQ Page |
| 3FGM.CO.90.40.7V/1 | 3FGM.CO.90.40.7V/1 40101728/50 40171207 Original Spare Part | Open Product RFQ Page |
| 3FL | 3FL 190-50 3V | Open Product RFQ Page |
| 3FL25-45 | 3FL25-45 3V NA | Open Product RFQ Page |
| 3FL40.40.3VNA | 3FL40.40.3VNA 40107102 Motor | Open Product RFQ Page |
| 3FL50-30/1 | 3FL50-30/1 | Open Product RFQ Page |
| 3HOEM550.89.6.3V | 3HOEM550.89.6.3V 40101194/50 MOTOR | Open Product RFQ Page |
| 3RB | 3RB 75-50-6V FCU MOTOR | Open Product RFQ Page |
| 3RG8 | 3RG8 50-30-6V/14 not available, alternative 3RGB45.30.6V.2 + capacitor ref.22321095 | Open Product RFQ Page |
| 3RGB | 3RGB 35-20-6V/4 38-00 obsolete, alternative 3RGB45.30.6V.2 Fan coil motor | Open Product RFQ Page |
| 3RGB-35-20/3V | 3RGB-35-20/3V 220V-50HZ-34/18W 0,44/0,30A Motor for fan coil | Open Product RFQ Page |
| 3RGB35.20.3V/1 | 3RGB35.20.3V/1 "MT1510" 40101292 Motor | Open Product RFQ Page |
| 3RGB45.30.6V.2 | 3RGB45.30.6V.2 | Open Product RFQ Page |
| 3RGB50.30.6V/14 | 3RGB50.30.6V/14 4010694 not available, alternative 3RGB55.30.6V/16 FAN MOTOR | Open Product RFQ Page |
| 3RGB55.30.6V/16 | 3RGB55.30.6V/16 | Open Product RFQ Page |
| 3RGB65.30.6V/1 | 3RGB65.30.6V/1 Motor | Open Product RFQ Page |
| 3RGB75.50.6V/2 | 3RGB75.50.6V/2 40101514 MOTOR | Open Product RFQ Page |
| 3RGB75.50.6V/3 | 3RGB75.50.6V/3 40101764 Motor | Open Product RFQ Page |
| 3RGB.CO.30.20/2 | 3RGB.CO.30.20/2 | Open Product RFQ Page |
| 3RGBI | 3RGBI 80-45-3V/2 4-019-1427 obsolete, replaced by B.A08.000.C Motor | Open Product RFQ Page |
| 3RGM | 3RGM 30-20-6V/2 | Open Product RFQ Page |
| 3RGM30.20 | 3RGM30.20 | Open Product RFQ Page |
| 3RGM30.20.6V/2 | 3RGM30.20.6V/2 4010692 -0692009936- Motor | Open Product RFQ Page |
| 3RGM40.20.0/3 | 3RGM40.20.0/3 40101605 motor | Open Product RFQ Page |
| 3RGM70.30/35 | 3RGM70.30/35 Motor | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|-------------------|---|---------------------------------------|
| 40101492 | 40101492 type motor 3 BTB 50-40-6V-0/ 2 | Open Product RFQ Page |
| 40101798/50 | 40101798/50 Motor | Open Product RFQ Page |
| 40101842/50 | 40101842/50 - not available, replaced by 3FGB 370.70.3V/8 motor | Open Product RFQ Page |
| 4017-1463 | 4017-1463 | Open Product RFQ Page |
| 4-017-1612 | 4-017-1612 OEM!! Fan type: 3FGB-CO 380-69-6V/1 | Open Product RFQ Page |
| 4-017-1633 | 4-017-1633 Fancoil fan | Open Product RFQ Page |
| 4-019-515 | 4-019-515 obsolete, alternative DD 10/8 M91E 1F 6P 3V (brand Nicotra) Fan | Open Product RFQ Page |
| 4-056-045 | 4-056-045 OEM | Open Product RFQ Page |
| 5850P8-P4PR-1000 | 5850P8-P4PR-1000 | Open Product RFQ Page |
| 6-13 | 6-13 - replaced by NET5T05ZVN001 ELECTROMOTOR FOR REFRIGERATOR GRAM A/S 6500 VOJENS | Open Product RFQ Page |
| 8016 | 8016 56 FEMALE | Open Product RFQ Page |
| 8450.B3 | 8450.B3 Motor | Open Product RFQ Page |
| 84FB50-6V | 84FB50-6V | Open Product RFQ Page |
| 8F8522 | 8F8522 Original Spare Part | Open Product RFQ Page |
| 984-23487-00 | 984-23487-00 Cooling Fan (thermally protected) Model No: Nu 16-30-2/103 P/N: NET4T16PUN301 115 volt, 50/60 Hz 16W, 1Amp , 1550RPM | Open Product RFQ Page |
| A83B-2015 | A83B-2015 Fan coil motor | Open Product RFQ Page |
| A83M-2525 | A83M-2525 Fan coil motor | Open Product RFQ Page |
| AML-PLC | AML-PLC | Open Product RFQ Page |
| B58C10-P66PR-1024 | B58C10-P66PR-1024 ELCO Drehgeber | Open Product RFQ Page |
| B.A08.000.C | B.A08.000.C motor | Open Product RFQ Page |
| BTNB41TB0098 | BTNB41TB0098 Motor | Open Product RFQ Page |
| BTNB41TB0120S | BTNB41TB0120S | Open Product RFQ Page |
| BTNM46TB0142 | BTNM46TB0142 | Open Product RFQ Page |
| CNN5U05NNB101 | CNN5U05NNB101 CN 5-20/009 fan | Open Product RFQ Page |
| Cod. | Cod. 4017-1236 Motor | Open Product RFQ Page |
| code | code 12201620 (price for 20 pcs) | Open Product RFQ Page |
| COND | COND 2 MF. Condensator | Open Product RFQ Page |
| condenser | condenser for 3BTB35.30.6V.0.1 condenser | Open Product RFQ Page |
| COND.P. | COND.P. 3.15µF 400V-6.35-25x5 Condensator | Open Product RFQ Page |
| COND.P.3.15µF | COND.P.3.15µF 400V-6.35 - 28x5 capacitor | Open Product RFQ Page |
| DA146x240CW | DA146x240CW | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|--------------------------------------|--|---------------------------------------|
| DEEF43BB02 | DEEF43BB02 Motor | Open Product RFQ Page |
| EAB58A10-GC6PHR-256+L5HR-1000.3L3703 | EAB58A10-GC6PHR-256+L5HR-1000.3L3703 OEM!! ELCO Drehgeber, Spezialausführung | Open Product RFQ Page |
| EAC58C10-GP6PAD R-4096E | EAC58C10-GP6PADR-4096E | Open Product RFQ Page |
| EAC58C10-GP6PPD R-1024 | EAC58C10-GP6PPDR-1024 BT encoder | Open Product RFQ Page |
| EB38F8-H4AR-1024.3H1201 | EB38F8-H4AR-1024.3H1201 encoder | Open Product RFQ Page |
| eb50a8 | eb50a8 c4dr 2500 YD132872 /30 / | Open Product RFQ Page |
| EB58C10-P4PR-300 | EB58C10-P4PR-300 | Open Product RFQ Page |
| EBM | EBM TKIN. BG5 Alternative Original Spare Part | Open Product RFQ Page |
| EC40A6-L5AR-1000 | EC40A6-L5AR-1000 ELCO Encoder | Open Product RFQ Page |
| EC40A6-L5AR-1000.1N0800 | EC40A6-L5AR-1000.1N0800 | Open Product RFQ Page |
| EC40A6-P4AR-600 | EC40A6-P4AR-600 110 g | Open Product RFQ Page |
| EC50A10-H6M8R-2500.9M5004 | EC50A10-H6M8R-2500.9M5004 Encoder | Open Product RFQ Page |
| EC50A8-P6PR-1000.5L6100 | EC50A8-P6PR-1000.5L6100 Encoder | Open Product RFQ Page |
| EC88P30-L5PP-1024 | EC88P30-L5PP-1024 Encoder | Open Product RFQ Page |
| ECM | ECM 12-15.C2M.VC.HC Motor | Open Product RFQ Page |
| ECM12-15 | ECM12-15 COD.EBA12150NA0058 - not available, replaced by ECM 12-15.C2M.VC.HC Fan | Open Product RFQ Page |
| EFCR | EFCR 10A FAN Motor | Open Product RFQ Page |
| EL | EL 01A.3H | Open Product RFQ Page |
| EM-4-50/3DS | EM-4-50/3DS | Open Product RFQ Page |
| EM-4-50/6DS | EM-4-50/6DS | Open Product RFQ Page |
| EVRC4I5A35S.1 | EVRC4I5A35S.1 Lüfter Motor | Open Product RFQ Page |
| Fan | Fan Coil ELCO Electric motor: 40171809 | Open Product RFQ Page |
| FC83M-2025/2 | FC83M-2025/2 Original Spare Part | Open Product RFQ Page |
| FGFM45TB0213S | FGFM45TB0213S | Open Product RFQ Page |
| FI4-M12-OP6L-Q12 | FI4-M12-OP6L-Q12 Induktiver Sensor | Open Product RFQ Page |
| FL | FL 45-40 1V Fan Coil Motor | Open Product RFQ Page |
| GMV | GMV 3RGB.CO.60.30.4V/3 40171652 FAN | Open Product RFQ Page |
| HAF162 | HAF162 0706100 Condenser Fan Motor | Open Product RFQ Page |
| HAF208 | HAF208 1106700488 Condenser Fan Motor | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|-------------------------|--|---------------------------------------|
| HRN-57 | HRN-57 relay | Open Product RFQ Page |
| impeller | impeller for 3BTB-CO 55-45-0/1 | Open Product RFQ Page |
| impellers | impellers for 3BTM-CO 15-20-0/12, alternative 3BTM25.20-A-0/122+ 22321095 | Open Product RFQ Page |
| K25AU-S | K25AU-S 85-125V 47-440HZ P■N 39W MAX 5V5A | Open Product RFQ Page |
| K35610MO1821 | K35610MO1821 Motor | Open Product RFQ Page |
| LMIX2-000-01.5-1-00 | LMIX2-000-01.5-1-00 sensor | Open Product RFQ Page |
| M29 | M29 X 90 FIT SCREW, Equipment Model Number : XSOHV 285V, Part Position / Item Number : 12 Sub Assembly rawing Number : 211-11018-0016, | Open Product RFQ Page |
| MA58 | MA58 10W 2500T A | Open Product RFQ Page |
| MA58.1.12.100.SF | MA58.1.12.100.SF 4032010, alternative MA58 10W 2500T S or MA58 10W 2500T A | Open Product RFQ Page |
| Mod | Mod 3 BTB 50-40-6V-0/1 Lüftermotor mit beidseitiger Lange Welle | Open Product RFQ Page |
| Mod:1BT | Mod:1BT 40-40-4V NA, Cod:BTNB44TC0166R obsolete/replaced with 3FL 40-40 3V NA + Shaft adapter Original Spare Part | Open Product RFQ Page |
| MOD.3 | MOD.3 FGB 100-40-6V/20 obsolete, alternative 3FGB100.40.6V.26 Motor | Open Product RFQ Page |
| MOD.3BTB | MOD.3BTB 40-40-A-0/5 not available, alternative 3BTB50.40.6V.0.1+ 22321101 or 3BTB50.40.6V.0.2 + 22321101 Motor | Open Product RFQ Page |
| Model: | Model: 3FGB 195-50-5V/3 - obsolete, replaced by 48-4-180/6DS (Remco) Motor | Open Product RFQ Page |
| MODEL:3BTM-0015-20-0/12 | MODEL:3BTM-0015-20-0/12 CODE:4-017-1540 FAN COIL RADIAL ENGINE | Open Product RFQ Page |
| MODEL:3FGM | MODEL:3FGM 110-40-6V/1 Obsolete, replaced by 3FL 50110/6Q Fan motor | Open Product RFQ Page |
| MOTOR-FAN | MOTOR-FAN UNITS 3BTEB-CO-35-30-4V/1 230V, 50Hz, 108Watt, 0.53 A, C = 2microF, 450V, at least 3 speeds | Open Product RFQ Page |
| MS71A2 | MS71A2 Fan | Open Product RFQ Page |
| N°: | N°: 2J50-24, N°: 2MZS02829 SWITCHING POWER SUPPLY 24 V, 2.5 A, INPUT: 95-370 VFOR TOSHIBA MAGNETIC CONTROLLER | Open Product RFQ Page |
| NET3T25NNN204 | NET3T25NNN204 COOLING FAN | Open Product RFQ Page |
| NET4T16PUN301 | NET4T16PUN301 Electro Motor | Open Product RFQ Page |
| NET5T05ZVN001 | NET5T05ZVN001 motor | Open Product RFQ Page |
| NET5T16PVN001 | NET5T16PVN001 | Open Product RFQ Page |
| NET5T18PVN001 | NET5T18PVN001 | Open Product RFQ Page |
| NGZMU | NGZMU 271 COUPLING RUBBER | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|-----------------|---|---------------------------------------|
| NU | NU 16-30-4 / 1285 fan motor | Open Product RFQ Page |
| OP18-K200VN6 | OP18-K200VN6 Opti-electric Sensor | Open Product RFQ Page |
| PASSED | PASSED 743 Original Spare Part | Open Product RFQ Page |
| Plastic | Plastic fan wheel for 3BTM-CO 25-20-0/22/ | Open Product RFQ Page |
| P/N | P/N N.OH 247 -285 W TRANSMITTING BOLT, COUPLING, Equipment Model Number : XSOHV 285V Part Diameter : DXL= 24.8 X 147 MM,Sub Assembly Drawing Number : | Open Product RFQ Page |
| R | R 18-25 2P MOTORE | Open Product RFQ Page |
| R18.25/001 | R18.25/001 RET2T18PNN001 Motor | Open Product RFQ Page |
| R18-25/009 | R18-25/009 motor | Open Product RFQ Page |
| Ref | Ref :12301059 turbine | Open Product RFQ Page |
| Reg | Reg Nr 4642, NET3T25PVN004 - replaced by 1516000573 - VNT25.40/030 300mm diameter fan assembly with a moto | Open Product RFQ Page |
| RET2T18PNN001 | RET2T18PNN001 | Open Product RFQ Page |
| RET4T18PNN001 | RET4T18PNN001 | Open Product RFQ Page |
| SC3-12D25480A | SC3-12D25480A 3,5kW Solid State Relay (HEATER 380V) | Open Product RFQ Page |
| SC3-12D50480A | SC3-12D50480A Solid State Relays 6kW (HEATER 380V) | Open Product RFQ Page |
| SD-0824A | SD-0824A RELE' STATICI | Open Product RFQ Page |
| SDP | SDP 0624A | Open Product RFQ Page |
| SSR | SSR 91-60B | Open Product RFQ Page |
| SSR08-25480AS | SSR08-25480AS | Open Product RFQ Page |
| SSR20-524B | SSR20-524B relay | Open Product RFQ Page |
| SSR20-524D-1 | SSR20-524D-1 RELE' STATICI | Open Product RFQ Page |
| SSR860-50480ASL | SSR860-50480ASL Solid State Relay | Open Product RFQ Page |
| SSR-90-240B | SSR-90-240B | Open Product RFQ Page |
| TBA | TBA 196/274 Fan Blower | Open Product RFQ Page |
| Type: | Type: 3BTB-CO 35-40-A-0/1 fan motor | Open Product RFQ Page |
| VG | VG 3.360 DP Original Spare Part | Open Product RFQ Page |
| VG3.290D | VG3.290D 3832897D-X02-000773 603 TCG 2XX control unit | Open Product RFQ Page |
| VN10.20/028 | VN10.20/028 NET5T10ZVN001, not available - replaced by VN10.20.028BI motor | Open Product RFQ Page |
| VN10.20.028BI | VN10.20.028BI Motor | Open Product RFQ Page |
| VN-10-20/122 | VN-10-20/122 alternative VN10.20/028 NET5T10ZVN001 Motor | Open Product RFQ Page |
| VNT | VNT 25-40/373 | Open Product RFQ Page |
| VNT2540/1346 | VNT2540/1346 FAN, DIAMETER:25CM , 230V, 95W | Open Product RFQ Page |

| Part Number | Product Description | Live RFQ Link |
|---------------|--|---------------------------------------|
| VNT34-45/1432 | VNT34-45/1432 | Open Product RFQ Page |
| Wing | Wing for BTNB41TB0098 | Open Product RFQ Page |
| Wiring | Wiring diagram MOD.3BTB 50-40-A/1,obsolete,replacement by 8450.B3 wiring diagram | Open Product RFQ Page |
| WSOMW | WSOMW Coopling | Open Product RFQ Page |
| Z000230 | Z000230 MOTORE ELCO R 18-25 2P CON CONDENSATORE | Open Product RFQ Page |

Axiparts Offices

Germany Head Office: Lise-Meitner-Straße 13, 89081 Ulm, Germany

USA Office: 16225 Park Ten Pl #500, Houston, TX 77084, United States

Dubai Office: HDS Business Centre Tower, Cluster M, 33rd Floor, Jumeirah Lake Towers, Dubai, United Arab Emirates