

# Liquiflo Industrial Parts Catalog

## Axiparts Global Industrial RFQ Platform

Email: [info@axiparts.com](mailto:info@axiparts.com)

Website: <https://axiparts.com>

Premium RFQ catalog for Liquiflo industrial spare parts, MRO components and replacement products. Every listed product is linked directly to its live RFQ product page.

**Brand:** Liquiflo

**Listed Products in This PDF:** 25

**Catalog URL:** <https://axiparts.com/catalogs/brands/liquiflo.pdf>

| Part Number                 | Product Description   | Live RFQ Link                         |
|-----------------------------|---|---------------------------------------|
| 316                         | 316 POMPA Original Spare Part                                 | <a href="#">Open Product RFQ Page</a> |
| 35FX6P3P300000SS            | 35FX6P3P300000SS obsolete, replaced by 35FX6P3P300000US Pump  | <a href="#">Open Product RFQ Page</a> |
| 35FX6P3P300000US            | 35FX6P3P300000US ROTOGEAR                                     | <a href="#">Open Product RFQ Page</a> |
| H7NX6PEE202000US8           | H7NX6PEE202000US8 0,37/1500/TF Edelst./PEEK/Carbon/TC/100 ° C | <a href="#">Open Product RFQ Page</a> |
| H7RS6PEEU000001-8/BARESHAFT | H7RS6PEEU000001-8/BARESHAFT pump                              | <a href="#">Open Product RFQ Page</a> |
| KH7NX6PEE202000US-8         | KH7NX6PEE202000US-8 REPAIR KIT DOSING PUMP REPAIR KIT MALE    | <a href="#">Open Product RFQ Page</a> |
| LI-310596                   | LI-310596 (LIQUIFLO WEAR PLATE)                               | <a href="#">Open Product RFQ Page</a> |
| LI-310685                   | LI-310685 (LIQUIFLO DRIVE GEAR, STAINLESS STEEL)              | <a href="#">Open Product RFQ Page</a> |
| LI-340416                   | LI-340416 (LIQUIFLO SHORT BEARING)                            | <a href="#">Open Product RFQ Page</a> |
| LI-340423                   | LI-340423 (LONG BEARING, LIQUIFLO REPLACES 340403)            | <a href="#">Open Product RFQ Page</a> |
| LI-341102                   | LI-341102 (LIQUIFLO TEFLON HOUSING, O-RING)                   | <a href="#">Open Product RFQ Page</a> |
| LI-346702                   | LI-346702 (LIQUIFLO RETAINING RING)                           | <a href="#">Open Product RFQ Page</a> |
| LI-351534                   | LI-351534 (LIQUIFLO SEAL SEAT)                                | <a href="#">Open Product RFQ Page</a> |
| LI-361801                   | LI-361801 (PIN, BEARING LOCK, PTFE, LIQUIFLO)                 | <a href="#">Open Product RFQ Page</a> |
| LI-45S6333N100              | LI-45S6333N100  | <a href="#">Open Product RFQ Page</a> |
| LI-H7NX6PEE202000US         | LI-H7NX6PEE202000US Original Spare Part                       | <a href="#">Open Product RFQ Page</a> |
| LI-H7RX6PEE202000US         | LI-H7RX6PEE202000US Pump                                      | <a href="#">Open Product RFQ Page</a> |
| LI-K35FX6333000000US        | LI-K35FX6333000000US Arbeitskammer                            | <a href="#">Open Product RFQ Page</a> |
| LI-K35FX6P3P300000US        | LI-K35FX6P3P300000US REPAIR KIT                               | <a href="#">Open Product RFQ Page</a> |

| Part Number          | Product Description   | Live RFQ Link                         |
|----------------------|---|---------------------------------------|
| LI-KH7NX6PEE202000US | LI-KH7NX6PEE202000US  | <a href="#">Open Product RFQ Page</a> |
| LI-KH7RX6PEE202000US | LI-KH7RX6PEE202000US  | <a href="#">Open Product RFQ Page</a> |
| LI-SOMCU-71          | LI-SOMCU-71 Pump repair kit magnet hive                             | <a href="#">Open Product RFQ Page</a> |
| REPAIR               | REPAIR KIT H7RS6PEEU000001-8 Original Spare Part                    | <a href="#">Open Product RFQ Page</a> |
| SVA008254            | SVA008254 H5FS6PEEU000001-8(266°F)<br>Edelst./Peek/GLRD: Carbon/SIC | <a href="#">Open Product RFQ Page</a> |
| TYPE                 | TYPE H1FL663E4F006060 di■li pompa motorlu                           | <a href="#">Open Product RFQ Page</a> |

### Axiparts Offices

Germany Head Office: Lise-Meitner-Straße 13, 89081 Ulm, Germany

USA Office: 16225 Park Ten Pl #500, Houston, TX 77084, United States

Dubai Office: HDS Business Centre Tower, Cluster M, 33rd Floor, Jumeirah Lake Towers, Dubai, United Arab Emirates